## **Funds Distribution Report**

## Recipient Organization: Tulalip Tribes Utilities

**Address:** 3015 Mission Beach Rd Tulalip, WA 98271

**Contact:** (360) 716-4840 https://www.tulaliptribes-nsn.gov/Dept/TulalipUtilities

## **Organization's General Goals:**


The Tulalip Utilities Department is dedicated to protect the health and welfare of the residing residents, businesses, and visitors. To provide quality services within available resources to our customers in a timely and efficient manner. To provide support in our development and economic growth.

. . . . . . . . . . . . . . . . . . .

Date of Award:	
2021 Q1	

**Level:** \$10,000+


For more information, please read the attached report from Tulalip Tribes Utilities.



8802 27th Ave NE Tulalip, WA 98271

## TulalipCares.org

Disclaimer: This report may be a summary of content provided by the recipient, not always complete quoted material. Annual Report Tulalip Cares Grant



3/01/2020

The Following report is a compilation of 15 of the 20 separate reports for projects funded by the grant. These stories detail the assistance and methods, and cooperation used during the past two years of funding from the Tulalip Cares grant.

The Tulalip cares grant was the motivation and spark to assist an estimated 100 Tribal members to resume a normal lifestyle. The grant assisted large tribal families, and smaller families. The grant assisted the Tribal members in restoring a functional and sanitary wastewater at would be an unplanned event and substantial financial impact on the Tribal member.

All assessments, ordering of repairs and permitting when necessary were made by the Tulalip Tribal Sanitarian.

These stories are examples of both the grants ability to correct impacts to the Tribal environment band show the grants capability to need to bring back and restore what were previously deficient wastewater treatment systems.

1. and Estuary protection 2. , Tribal vet and Elder 3. Septic pump repair the land that sewer forgot 4. a home in poor condition 5. 6. another modern addition to an old system 7. Tank hits tree and the tank lost Too FAST and too far an ATU restoration project 8. How to pump the tank down through a damaged d box and other neat tricks. 9. Pressure line manifold brakes 10. Tribal Elder replacement of drainfield. (originally denied Indian Health) 11. assistance as home was HUD). Assess, design, and install field 12. Full drainfield and pump replacement. 14 residents in home, assess, design and provide materials for the project. 13. Installation by construction. (cooperative project) Substantially damaged drainfield repaired broken field line ends 14.

J. Dongles Dafie RS.